

Worksheet - Cover Page

Printed: June 21, 2002, 2:53 PM

Company: Safetech

Location: Princeton, NJ

Facility: Princeton

PHA Method: HAZOP

PHA Type: Initial

Process:

File Description:

Chlorine Handling

Date:

Process Description:

Chemicals:

Purpose:

Scope:

Objectives:

Project Notes:

Filters: None

Worksheet

Company: Safetech
 Facility: Princeton

Session: (1) 07/02/00
 Node: (1) Chlorine rail car
 Drawings: CLC/01-07-66
 Parameter: Pressure

Revision: 0

Intention: Normal operation is 100 - 150 psig. Target pressure is 125 psig.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
More	Higher Pressure	1. Fire exposure	1.1. Potential overpressurization of rail car resulting in release of chlorine.	1.1.1. Rail cars provided with relief valve. 1.1.2. Rail cars insulated	1	4	4		:No recommendations	
			1.2. Potential rupture of the rail car if the rail car relief valve fails.	1.2.1. Location of rail car minimizes likelihood of exposure.	1	5	5		:No recommendations	
		2. High ambient temperature	2.1. Potential increase in pressure. Not likely to approach rated pressure of rail car.	2.1.1. Rail cars insulated 2.1.2. Location of rail car minimizes likelihood of exposure. 2.1.3. Pressure indicator, PI-1.	5	1	5		:No recommendations	
Less	Lower Pressure	3. Relief valve RV-25 fails open	3.1. Potential exposure of personnel and potential offsite impact	3.1.1. Railcar emergency leak patch kit is available on site. 3.1.2. Pressure indicator, PI-1.	1	4	4		3.1.1. Consider conducting a failure modes and effects analysis (FMEA) of a typical pressure relief valve.	PWP
		4. Empty rail car	4.1. Delay in treating	4.1.1. Rail car is weighed upon receipt	5	3	9		:No further recommendations	
		5. Sudden change in ambient temperature	5.1. Potential for too low flow to the treatment system	5.1.1. Rail cars insulated	5	2	8		:No further recommendations	

Session: (1) 07/02/00
 Node: (1) Chlorine rail car
 Drawings: CLC/01-07-66
 Parameter: Composition

Revision: 0

Intention: Chlorine with less than 5 ppm moisture.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
Other Than	Other Than Composition	1. Supplier loads rail car with incorrect material	1.1. Consequences will depend upon what other materials could be delivered in rail...	1.1.1. Analysis of shipment by supplier.	3	4	8		1.1.1. Consider changing the SOP to require a certificate of analysis be received with each rail car and...	DSC

Worksheet

Company: Safetech
 Facility: Princeton

Session: (1) 07/02/00
 Node: (1) Chlorine rail car
 Drawings: CLC/01-07-66
 Parameter: Composition

Revision: 0

Intention: Chlorine with less than 5 ppm moisture.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
Other Than (cont.)	Other Than Composition (cont.)	1. Supplier loads rail car with incorrect material (cont.)	...cars.	1.1.1. Analysis of shipment by supplier. (cont.)					...be checked before accepting the rail car.	
As Well As	As Well As Composition (contamination)	2. Rail car padded with incorrect material (e.g. moist air) by supplier	2.1. Moisture with chlorine will cause accelerated corrosion of system piping	2.1.1. Analysis of shipment by supplier.	3	4	8		:No further recommendations	
			2.2. Consequences will depend upon what other materials could be delivered in rail cars	2.2.1. As for 2.1.1	3	4	8		:No further recommendations	

Session: (1) 07/02/00
 Node: (1) Chlorine rail car
 Drawings: CLC/01-07-66
 Parameter: Level

Revision: 0

Intention: Normal railcar liquid level varies between a maximum of 80 % of capacity to as empty as practical.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
No	No Level	1. Rail car received empty	1.1. Delay in treating	1.1.1. Rail car is weighed upon receipt	5	4	10		:No recommendations	
		2. Leak in rail car or attached piping	2.1. Potential exposure of personnel and potential offsite impact	2.1.1. Chlorine gas sensors around rail car unloading station 2.1.2. Emergency C kit available for rail car leaks	3	4	8		:No recommendations	
More	Higher Level	3. Supplier overloads	3.1. Potential overpressure of rail car due to thermal expansion of material	3.1.1. Rail car weighed upon receipt	3	4	8		3.1.1. *Verify the scales are calibrated correctly	LSS

Worksheet

Company: Safetech
 Facility: Princeton

Session: (1) 07/02/00
 Node: (2) Cl₂ liquid to vaporizer
 Drawings: CLC/01-07-66
 Parameter: Flow

Revision: 0

Intention: Flow approximately 1 - 5 lbs/min of liquid chlorine, at 100- 150 psig, from the railcar to the vaporizer.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
No	No Flow	1. Control valve CV-32 fails closed	1.1. Interruption to production operation due to deviation of Cl ₂ flow from setpoint causing control system to shut down process	1.1.1. Failing closed, or accidentally closing, a single valve will not result in overpressure since line is open to either end 1.1.2. Operator response to a shutdown of the system would be immediate 1.1.3. Limit switch provided on each valve which will indicate the valve is closed 1.1.4. Micromotion flow meter, FTLIQA	4	4	9		:No recommendations	
			1.2. Potential overpressure of Cl ₂ piping if liquid-filled, closed piping heats up	1.2.1. All valves (ball valves) in liquid Cl ₂ service are provided with a port to vent the ball cavity 1.2.2. Rupture disk discharging to expansion tanks are provided for the section of the piping between - VLIQA and VLIQB - PCVGASC and PCVGASB (downstream of vaporizer) 1.2.3. Pressure transmitters provided on potentially trapped sections of piping between: - VRCA2 and VRCL - VRCB2 and...	3	4	8		:No recommendations	

Worksheet

Company: Safetech
 Facility: Princeton

Session: (1) 07/02/00
 Node: (2) Cl₂ liquid to vaporizer
 Drawings: CLC/01-07-66
 Parameter: Flow

Revision: 0

Intention: Flow approximately 1 - 5 lbs/min of liquid chlorine, at 100- 150 psig, from the railcar to the vaporizer.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
No (cont.)	No Flow (cont.)	1. Control valve CV-32 fails closed (cont.)	1.2. Potential overpressure of Cl ₂ piping if liquid-filled, closed piping heats up (cont.)	...VRCM - VRCL/M and VLIQA - VLIQB and PCVGASC					:No recommendations (cont.)	
		2. Control system incorrectly activates shutdown for "rupture" condition	2.1. Potential overpressure of Cl ₂ piping if liquid filled, closed piping heats up	2.1.1. Rupture disk discharging to expansion tanks are provided for the section of the piping between - VLIQA and VLIQB - PCVGASC and PCVGASB (downstream of vaporizer) 2.1.2. Failing closed, or accidentally closing, a single valve will not result in overpressure since line is open to either end 2.1.3. Limit switch provided on each valve which will indicate the valve is closed 2.1.4. Micromotion flow meter, FTLIQA	3	4	8		2.1.1. *Investigate the design of the rupture disks and expansion tanks and the pressure setting (375 psig) of the rupture disk 2.1.2. *Verify Chlorine Institute requirements for venting valves with design of existing valves	LDS JBS
		3. Control valve closes due to incorrect signal or setting	3.1. Interruption to production operation due to deviation of Cl ₂ flow from setpoint causing control system to shut down process	3.1.1. Failing closed, or accidentally closing, a single valve will not result in overpressure since line is open to either end 3.1.2. Operator response to a shutdown of the system would be immediate	4	4	9		:No further recommendations	

Worksheet

Company: Safetech
 Facility: Princeton

Session: (1) 07/02/00
 Node: (2) Cl₂ liquid to vaporizer
 Drawings: CLC/01-07-66
 Parameter: Flow

Revision: 0

Intention: Flow approximately 1 - 5 lbs/min of liquid chlorine, at 100- 150 psig, from the railcar to the vaporizer.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
No (cont.)	No Flow (cont.)	3. Control valve closes due to incorrect signal or setting (cont.)	3.1. Interruption to production operation due to deviation of Cl ₂ flow from setpoint causing control system to shut down process (cont.)	3.1.3. Limit switch provided on each valve which will indicate the valve is closed 3.1.4. Micromotion flow meter, FTLIQA					:No further recommendations (cont.)	
		4. Manual block valve is accidentally closed	4.1. Interruption to production operation due to deviation of Cl ₂ flow from setpoint causing control system to shut down process	4.1.1. Failing closed, or accidentally closing, a single valve will not result in overpressure since line is open to either end 4.1.2. Operator response to a shutdown of the system would be immediate 4.1.3. Limit switch provided on each valve which will indicate the valve is closed 4.1.4. Micromotion flow meter, FTLIQA	4	4	9		:No further recommendations	
		5. Filter plugged	5.1. Interruption to production operation due to deviation of Cl ₂ flow from setpoint causing control system to shut down process	5.1.1. Operator response to a shut down of the system would be immediate 5.1.2. Micromotion flow meter, FTLIQA	4	2	7		:No further recommendations	
		6. Micromotion meter plugged	6.1. Interruption to production operation due to deviation of Cl ₂ flow from setpoint causing control...	6.1.1. Operator response to a shut down of the system would be immediate 6.1.2. Pressure...	4	2	7		:No further recommendations	

Worksheet

Company: Safetech
 Facility: Princeton

Session: (1) 07/02/00
 Node: (2) Cl₂ liquid to vaporizer
 Drawings: CLC/01-07-66
 Parameter: Flow

Revision: 0

Intention: Flow approximately 1 - 5 lbs/min of liquid chlorine, at 100- 150 psig, from the railcar to the vaporizer.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
No (cont.)	No Flow (cont.)	6. Micromotion meter plugged (cont.)	...system to shut down process	...transmitters before and after the meter					:No further recommendations (cont.)	
		7. Dip pipe (in railcar) plugged	7.1. Interruption to production operation due to deviation of Cl ₂ flow from setpoint causing control system to shut down process	7.1.1. Operator response to a shut down of the system would be immediate 7.1.2. Micromotion flow meter, FTLIQA	4	2	7		:No further recommendations	
		8. Excess flow valve closed	8.1. Interruption to production operation due to deviation of Cl ₂ flow from setpoint causing control system to shut down process	8.1.1. Failing closed, or accidentally closing, a single valve will not result in overpressure since line is open to either end 8.1.2. Operator response to a shutdown of the system would be immediate 8.1.3. Micromotion flow meter, FTLIQA	4	4	9		:No further recommendations	
	9. Line or flex hose failure	9.1. Release of Cl ₂ to the atmosphere	9.1.1. Railcars inspected between each load by supplier 9.1.2. Chlorine gas sensors in the vicinity of the railcar and in the vaporizer building 9.1.3. Pressure along the piping is monitored by control system. If pressure differential exceeds 40-50 psig between 2 transmitters, control system will...	1	4	4		9.1.1. Consider alternatives to the present hanger arrangements to allow total insulating of the piping while minimizing external corrosion of the piping. 9.1.2. Consider whether alternative materials of construction are practical which will provide better internal and external corrosion resistance	LDS TLK	

Worksheet

Company: Safetech
 Facility: Princeton

Session: (1) 07/02/00
 Node: (2) Cl₂ liquid to vaporizer
 Drawings: CLC/01-07-66
 Parameter: Flow

Revision: 0

Intention: Flow approximately 1 - 5 lbs/min of liquid chlorine, at 100- 150 psig, from the railcar to the vaporizer.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
No (cont.)	No Flow (cont.)	9. Line or flex hose failure (cont.)	9.1. Release of Cl ₂ to the atmosphere (cont.)	...initiate a "line rupture" shutdown which closes all valves on the liquid Cl ₂ piping 9.1.4. Piping pressure tested prior to each campaign 9.1.5. Normal preventive maintenance program for Cl ₂ piping is to perform non-destructive testing of wall thickness annually					9.1.2. Consider whether alternative materials of construction are practical which will provide better internal and external corrosion resistance (cont.)	
Less	Less Flow	10. Block valve (VRCG/H, PCVLIQA) to vent scrubber system open or passing	10.1. Potential interruption to production if flow deviates significantly from setpoint 10.2. Potential release to the atmosphere if exceeds scrubber capacity or scrubber not operating	10.1.1. Second block valve, PCVLIQB, on vent line from railcar station would also have to be accidentally open or passing 10.1.2. Position switches provided on all valves leading to the scrubber system from the liquid chlorine lines (VRCG, VRCH, PCVLIQA, PCVLIQB) which indicate if the valve moves off the fully closed position. 10.2.1. All the valves from the liquid chlorine lines to the scrubber (VRCG, VRCH, PCVLIQA, PCVLIQB) are interlocked closed by the control system when...	4	4	9		:No further recommendations	
					1	4	4		:No further recommendations	

Worksheet

Company: Safetech
 Facility: Princeton

Page: 8 of 16

Session: (1) 07/02/00

Revision: 0

Node: (2) Cl₂ liquid to vaporizer

Drawings: CLC/01-07-66

Parameter: Flow

Intention: Flow approximately 1 - 5 lbs/min of liquid chlorine, at 100- 150 psig, from the railcar to the vaporizer.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
Less (cont.)	Less Flow (cont.)	10. Block valve (VRCG/H, PCVLIQA) to vent scrubber system open or passing (cont.)	10.2. Potential release to the atmosphere if exceeds scrubber capacity or scrubber not operating (cont.)	...chlorine is in the system, preventing the operator from accidentally manually opening the valve from the console.					:No further recommendations (cont.)	
		11. Partial pluggage of any component or partially closed valve	11.1. Potential interruption to production if flow deviates significantly from setpoint	11.1.1. Pressure transmitter, PTRCF, on vent line from railcar station would increase if upstream valve(s) passing and downstream closed 11.1.2. Temperature indication, TTLIQA, on vent line to flash pot may indicate lower temperature due flashing of Cl ₂ liquid	4	2	7		:No further recommendations	
	More Flow	12. Leak	12.1. Release of Cl ₂ to the atmosphere	12.1.1. Chlorine sensor provided near atmospheric vent from scrubber system 12.1.2. Control valve on Cl ₂ gas flow to reactor, FCVGASA, will open to attempt to maintain set flow to reactor	1	4	4		12.1.1. Review the best available means for periodic testing and/or examination of the chlorine liquid piping system to ensure the system integrity	PWP
	More Flow	13. N ₂ pressurization valve, VRCC/VRCD, opens during padding of railcar, and manual block on tubing left open, displacing liquid Cl ₂ in line with N ₂	13.1. Potential erratic flow due to presence of N ₂ in system. Potential overchlorination of product due to surge of chlorine ahead of N ₂ . Impact on product quality. Potential overloading of...	13.1.1. Flow indication and control (FICGASA) on chlorine flow to reactor will throttle to maintain set flow 13.1.2. Position indicators on N ₂ valves (VRCC, VRCD) which...	4	4	9		:No recommendations	

Worksheet

Company: Safetech
 Facility: Princeton

Page: 9 of 16

Session: (1) 07/02/00

Revision: 0

Node: (2) Cl₂ liquid to vaporizer

Drawings: CLC/01-07-66

Parameter: Flow

Intention: Flow approximately 1 - 5 lbs/min of liquid chlorine, at 100- 150 psig, from the railcar to the vaporizer.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
Less (cont.)	More Flow (cont.)	13. N ₂ pressurization valve, VRCC/VRCD, opens during padding of railcar, and manual block on tubing left open, displacing liquid Cl ₂ in line with N ₂ (cont.)	...scrubber	...indicates whenever the valve is off normally closed position.					:No recommendations (cont.)	
		14. Higher than normal pressure in rail car	14.1. Potential erratic flow due to presence of N ₂ in system. Potential overchlorination of product due surge of chlorine ahead of N ₂ . Impact on product quality. Potential overloading of scrubber	14.1.1. Backup manual valve on N ₂ line is normally closed except when pressure testing the piping. 14.1.2. Pressure monitoring of pipeline	4	4	9		:No recommendations	
		15. Flow control valve, FCVGASA, opens wide due to incorrect signal or setting	15.1. Potential erratic flow due presence of N ₂ in system. Potential overchlorination of product due surge of chlorine ahead of N ₂ . Impact on product quality. Potential overloading of scrubber	15.1.1. Independent flow indication, FTLIQA, to allow operator to verify flow control reading	4	4	9		:No recommendations	
		16. Sudden clearing of a blockage	16.1. Potential erratic flow due to presence of N ₂ in system. Potential overchlorination of product due surge of chlorine ahead of N ₂ . Impact on product quality. Potential overloading of...	16.1.1. Flow indication and control (FICGASA) on chlorine flow to reactor will throttle to maintain set flow	4	2	7		:No recommendations	

Worksheet

Company: Safetech
 Facility: Princeton

Session: (1) 07/02/00
 Node: (2) Cl₂ liquid to vaporizer
 Drawings: CLC/01-07-66

Revision: 0

Parameter: Flow

Intention: Flow approximately 1 - 5 lbs/min of liquid chlorine, at 100- 150 psig, from the railcar to the vaporizer.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
Less (cont.)	More Flow (cont.)	16. Sudden clearing of a blockage (cont.)	...scrubber due to surge of chlorine	16.1.1. Flow indication and control (FIGGASA) on chlorine flow to reactor will throttle to maintain set flow (cont.)					:No recommendations (cont.)	
Reverse	Reverse Flow	17. Blockage of the system downstream of the vaporizer	17.1. Vaporization of liquid in vaporizer will increase vaporizer pressure pushing liquid Cl ₂ back to rail car	17.1.1. Chlorine line is open back to the rail car preventing excessive pressure buildup 17.1.2. Pressure indication on vaporizer outlet, PTGASA	4	2	7		:No recommendations	
			17.2. No flow, sensed by FIGGASA, will initiate a shutdown. Will close VLIQB and open VGASA to vent vaporizer to the scrubber	17.2.1. Flow indicators, FIGGASA and FTLIQA, will indicate no flow 17.2.2. Line upstream of VLIQB is open to the railcar	4	2	7		:No recommendations	
		18. Rupture of the N ₂ pressurization line at the rail car when padding the rail car	18.1. Release of Cl ₂ to atmosphere	18.1.1. Piping downstream of vaporizer is vented to the scrubber thru VGASA 18.1.2. Rupture disk and relief valve on vaporizer, discharging to catch pot T-22, if blockage is between vaporizer and VGASA. Additional capability to manually vent lines thru VGASC or PCVLIQA	1	5	5		:No recommendations	
		19. Failure of liquid chlorine line or flex hose	19.1. Release of Cl ₂ to the atmosphere	19.1.1. Piping downstream of vaporizer is vented...	1	5	5		:No recommendations	

Worksheet

Company: Safetech
 Facility: Princeton

Session: (1) 07/02/00
 Node: (2) Cl₂ liquid to vaporizer
 Drawings: CLC/01-07-66
 Parameter: Flow

Revision: 0

Intention: Flow approximately 1 - 5 lbs/min of liquid chlorine, at 100- 150 psig, from the railcar to the vaporizer.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
Reverse (cont.)	Reverse Flow (cont.)	19. Failure of liquid chlorine line or flex hose (cont.)	19.1. Release of Cl ₂ to the atmosphere (cont.)	...to the scrubber thru VGASA 19.1.2. Rupture disk and relief valve on vaporizer, discharging to catch pot T-22, if blockage is between vaporizer and VGASA. Additional capability to manually vent lines thru VGASC or PCVLIQA					:No recommendations (cont.)	
Other Than	Other Than Flow	20. Failure of rupture disk on liquid line	20.1. Some flow of chlorine to the expansion tanks	20.1.1. Pressure indicator, PTLIQD, on line to expansion tanks	1	5	5		:No recommendations	
			20.2. Potential loss of expansion capacity if rupture disk released, expansion tanks filled and pressure rise in expansion tanks not observed by operator.	20.2.1. Chlorine gas sensors in the vicinity of the railcar and in the vaporizer building 20.2.2. Pressure along the piping is monitored by control system. If pressure differential exceeds 40-50 psig between 2 transmitters, control system will initiate a "line rupture" shutdown which closes all valves on the liquid Cl ₂ piping 20.2.3. Piping pressure tested prior to each campaign	4	5	10		:No recommendations	

Worksheet

Company: Safetech
 Facility: Princeton

Session: (1) 07/02/00
 Node: (2) Cl2 liquid to vaporizer
 Drawings: CLC/01-07-66
 Parameter: Pressure

Revision: 0

Intention: Normal operating pressure is approximately 100-145 psig.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
More	Higher Pressure	1. Fire exposure	1.1. Potential overpressurization of rail car resulting in release of chlorine.	1.1.1. Chlorine line insulated except at hangers	1	5	5		:No further recommendations	
				1.1.2. Chlorine line open to railcar and/or vaporizer						
			1.1.3. Rail cars insulated							
		1.2. Potential rupture of the rail car if the rail car relief valve fails.	1.2.1. Rail cars provided with relief valve	1	5	5		:No further recommendations		
1.2.2. Location of rail car minimizes likelihood of exposure										
1.2.3. Pressure indicator, PI-1										
	2. Steam exposure	2.1. Potential overheating if broken steam line discharges on chlorine line	2.1.1. Chlorine line insulated except at hangers	3	4	8		:No recommendations		
2.1.2. Chlorine line open to railcar and/or vaporizer										
2.1.3. Rail cars insulated										
	3. High ambient temperature	3.1. Potential increase in pressure. Not likely to approach rated pressure of rail car	3.1.1. Chlorine line insulated except at hangers	5	1	5		:No further recommendations		
3.1.2. Chlorine line open to railcar and/or vaporizer										
3.1.3. Rail cars insulated										
	4. Change in ambient temperature after padding rail car	4.1. Potential for too low flow to the treatment system	4.1.1. Chlorine line insulated except at hangers	5	2	8		:No further recommendations		
4.1.2. Chlorine...										

Worksheet

Company: Safetech
 Facility: Princeton

Page: 13 of 16

Session: (1) 07/02/00
 Node: (2) Cl2 liquid to vaporizer
 Drawings: CLC/01-07-66
 Parameter: Pressure

Revision: 0

Intention: Normal operating pressure is approximately 100-145 psig.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
More (cont.)	Higher Pressure (cont.)	4. Change in ambient temperature after padding rail car (cont.)	4.1. Potential for too low flow to the treatment system (cont.)	...line open to railcar and/or vaporizer 4.1.3. Pressure indicator, PI-1 4.1.4. Rail cars insulated					:No further recommendations (cont.)	
Less	Lower Pressure	5. Leak in rail car or relief valve fails open	5.1. Potential exposure of personnel and potential offsite impact	5.1.1. Railcar emergency leak patch kit is available on site 5.1.2. Pressure indicator, PI-1	1	5	5		:No further recommendations	
		6. Empty rail car	6.1. Delay in treating	6.1.1. Rail car weighed upon receipt	4	4	9		:No further recommendations	
		7. Sudden change in ambient temperature	7.1. Potential for too low flow to the treatment system	7.1.1. Rail car weighed upon receipt	4	3	8		:No further recommendations	

Session: (1) 07/02/00
 Node: (2) Cl2 liquid to vaporizer
 Drawings: CLC/01-07-66
 Parameter: Composition

Revision: 0

Intention: Chlorine to specification

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
As Well As	As Well As Composition	1. Water, or other agents, in line after cleaning	1.1. Potential for accelerated corrosion of the piping	1.1.1. Normal procedure for cleaning includes blowing the system dry with N ₂ after cleaning 1.1.2. Training of maintenance personnel working on chlorine system	3	4	8		1.1.1. Consider means of cleaning the chlorine piping system which do not involve the use of water or incompatible materials	LDS
		2. Use of non-compatible materials, such as hydrocarbon-containing greases, during maintenance of...	2.1. Potential reaction possibly causing accelerated corrosion, fire or contaminants affecting product quality	2.1.1. Normal procedure for cleaning includes blowing the system dry with N ₂ after cleaning	3	4	8		2.1.1. Consider modifying the training program for maintenance personnel who may work on the chlorine system to include coverage of...	TLK

Worksheet

Company: Safetech
 Facility: Princeton

Page: 14 of 16

Session: (1) 07/02/00
 Node: (2) Cl2 liquid to vaporizer

Revision: 0

Drawings: CLC/01-07-66

Parameter: Composition

Intention: Chlorine to specification

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
As Well As As (cont.)	As Well As Composition (cont.)	...system	2.1. Potential reaction possibly causing accelerated corrosion, fire or contaminants affecting product quality (cont.)	2.1.2. Training of maintenance personnel working on chlorine system					...incompatible materials	

Worksheet

Company: Safetech
Facility: Princeton

Page: 15 of 16

Session: (1) 07/02/00
Node: (3) Cl₂ vaporizer

Revision: 0

Drawings: CLC/01-07-66
Parameter: Flow

Intention: Vaporize 100-150 pounds per hour. Target is 125.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
No	No Flow	1. Exit valve is in off position	1.1. Overpressurization of vaporizer	1.1.1. Relief valves on vessel	3	4	8		1.1.1. *Verify relief valves undergo periodic testing	LSS
		2. Entrance valve is in off position	2.1. Product down time	2.1.1. None	4	4	9		:No further recommendations	
			2.2. Excessive wear on pumps	2.2.1. Pumps have autoshutoff switches to prevent overheating	3	4	8		:No further recommendations	
		As Well As	As Well As Flow	3. N ₂ purge stream valve is open	3.1. Impure product	3.1.1. Feed is tested when it is unloaded from rail car	4	4	9	
4. Impure Cl ₂ feed	4.1. Impure product			4.1.1. Feed is tested when it is unloaded from rail car	4	4	9		:No further recommendations	
			4.2. Side reaction causing exotherm.		3	4	8		:No further recommendations	

Session: (1) 07/02/00
Node: (3) Cl₂ vaporizer

Revision: 0

Drawings: CLC/01-07-66
Parameter: Pressure

Intention: Vaporizer is intended to operate at 3 atm.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
More	Higher Pressure	1. Exit line from vaporizer plugged	1.1. Failure to provide adequate supply to reactor	1.1.1. Low flow alarm present	4	2	7		:No further recommendations	
			1.2. Pressure build up in vaporizer	1.2.1. Pressure rating on vaporizer exceeds that of the supply tanks	4	2	7		:No further recommendations	
		2. Chlorine supply line has a greater flow rate than designed	2.1. Pressure build up in vaporizer	2.1.1. Pressure rating on vaporizer exceeds that of the supply tanks	3	4	8		:No further recommendations	
Less	Lower Pressure	3. Supply line plugged	3.1. Loss of productivity due to low chlorine supply to reactor	3.1.1. Low flow alarm present.	4	2	7		3.1.1. *Check to see if this has ever been a problem	LSS
		4. Rupture in line exiting the vaporizer	4.1. Release of chlorine to atmosphere	4.1.1. Chlorine gas sensors in the area	1	5	5		4.1.1. Consider installing an automatic chlorine source...	JBS

Worksheet

Company: Safetech
 Facility: Princeton

Page: 16 of 16

Session: (1) 07/02/00
 Node: (3) Cl₂ vaporizer

Revision: 0

Drawings: CLC/01-07-66
 Parameter: Pressure

Intention: Vaporizer is intended to operate at 3 atm.

GW	DEVIATION	CAUSES	CONSEQUENCES	SAFEGUARDS	S	L	R	REF#	RECOMMENDATIONS	BY
Less (cont.)	Lower Pressure (cont.)	4. Rupture in line exiting the vaporizer (cont.)	4.1. Release of chlorine to atmosphere (cont.)	4.1.1. Chlorine gas sensors in the area (cont.)					...shutdown if the vaporizer pressure drops below 1.5 atm.	
			4.2. Loss of reactant			4	5	1	0	:No further recommendations
		5. Leak in vaporizer	5.1. Release of Cl ₂ to atmosphere	5.1.1. Chlorine gas sensors in the area	1	5	5		5.1.1. Consider implementing a periodic check of vaporizer to ensure there are no pressure leaks	LDS

Worksheet - Index

Node 1: Chlorine rail car	1
Parameter: Pressure	1
Parameter: Composition	1
Parameter: Level	2
Node 2: Cl ₂ liquid to vaporizer	3
Parameter: Flow	3
Parameter: Pressure	12
Parameter: Composition	13
Node 3: Cl ₂ vaporizer	15
Parameter: Flow	15
Parameter: Pressure	15